

Sydenham House – Sefton - Liverpool



<u>Issue:</u>

Following a fire on the 14th Floor (Penthouse), the whole block of XXX properties were left without TV / Satellite signals owing to severe damage to the communal aerial / satellite distribution system.

Solution:

As residents began to be moved back into their properties it became apparent that the properties were left without distributed signals. Astbury's services were called on by Martin Tighe who knew that Astbury would be able re-instate signals to the dwellings.

This involved providing temporary power from another floor and rewiring various parts of the main head-end to provide signals. Also a replacement satellite dish was temporarily fitted on a balcony to introduce satellite signals back into the distribution system, and although the lift was still out of order this did not deter the Astbury engineer from climbing 26 flights of stairs multiple times to complete the works.



Conclusion:

The work that Astbury carried out allowed residents to move back into their properties and continue to watch television / satellite programs whilst the renovation works were carried out to the penthouse level, saving Your Housing a large amount of money rehousing residents while renovations are carried out

Astbury TV Aerials Limited (T/A Astbury)

Unit 6, Charlestown Industrial Estate Robinson Street, Ashton-under-Lyne Lancashire. OL6 &NS 0161 330 5700

Registered in England & Wales: 980805



service@astbury.co.uk www.astbury.co.uk